

jc525 U.S. PTO
09/533554

03/22/00

(Atty. Ref.: OPS Case 485)

[illegible]

SPECIFICATION

DRIVING UNIT OF A WELDING EQUIPMENT

5

BACKGROUND OF THE INVENTION

1. Field of the Invention:

The invention relates to a driving unit of a welding equipment capable of converting a rotary output of a motor into reciprocating motion of a pressure application shaft so that the pressure application shaft can operate a gun arm or a welding jig.

10

2. Related Art:

There is a known driving unit of a welding equipment provided with a pressure application shaft to be driven by a motor as disclosed, for example, in Japanese Utility Model Registration No. 3042268 and Patent Laid-Open Publication No. 9-144834, wherein a screw shaft is provided on an output shaft extended from a motor by way of a gear and a screw provided on one end of the screw shaft is screwed with a nut formed on the pressure application shaft (hereinafter referred to as a first prior art).

15

20

There is a further known driving unit of a welding equipment provided with a pressure application shaft to be driven by a motor as disclosed, for example, in Japanese Patent Laid-Open Publication No. 7-290251, wherein a rotary shaft of a motor is made hollow and a screw shaft is forced to penetrate this hollow portion so that a screw formed on the screw shaft is screwed with a nut fixed to the rotary shaft (hereinafter referred to as a second prior art).

25

However, in the first prior art, since the screw shaft is provided on the output shaft extended from the motor by way of a gear, a driving unit becomes complex and it becomes long in its entire length, resulting in a drawback of unstable

operation when operating a motor-operated welding equipment.

In the second prior art, although the length of the driving unit becomes long, the diameter of the motor becomes large because the nut is fixed to the rotary shaft of the motor inside the motor and also the moment of inertia becomes large because
5 the diameter of the nut is relatively larger than the screw of the screw shaft, thereby extending the acceleration and deceleration time of electrodes when the electrodes open and close as the motor operates.

SUMMARY OF THE INVENTION

10 The invention has been made in view of the problems of the conventional driving unit of a welding equipment, and it is a first object of the invention to provide a driving unit of a welding equipment capable of reducing the size of the driving unit and reducing the moment of inertia by integrating or substantially
15 integrating a rotary shaft of a motor and a screw shaft so that the driving unit of a welding equipment has an excellent operability.

It is a second object of the invention to provide a driving unit of a welding equipment capable of easily fixing a screw shaft to a rotary shaft by use of fixed means utilizing a friction force without requiring a troublesome operation such as shrinkage fit or cold shrinkage fit.

20 It is a third object of the invention to provide a driving unit of a welding equipment capable of securing the application of pressure to a workpiece by a pressure application shaft by disposing an elastic body on the axis of the pressure application shaft through which pressure application force exerts.

25 It is a fourth object of the invention to provide a driving unit of a welding equipment capable of moving a pressure application shaft to a desired standby position when a motor is troubled by forming a machining part for manually turning the screw shaft at the rear end side of the rotary shaft or screw shaft.

BRIEF DESCRIPTION OF THE DRAWINGS

Fig. 1 is a sectional view of a driving unit of a welding equipment according to a first embodiment of the invention;

Fig. 2 is a sectional view of a driving unit of a welding equipment according to a second embodiment of the invention;

Fig. 3 is a sectional view of a driving unit of a welding equipment according to a third embodiment of the invention;

Fig. 4 is a sectional view of a driving unit of a welding equipment according to a fourth embodiment of the invention;

Fig. 5 is sectional view of a driving unit of a welding equipment according to a fifth embodiment of the invention, particularly a view showing the detail of a machining part thereof on which a manually operating handle is mounted for manually operating the driving unit;

Fig. 6 is sectional view of a driving unit of a welding equipment according to a sixth embodiment of the invention, particularly a view showing the detail of a machining part thereof on which a manually operating handle is mounted for manually operating the driving unit; and

Fig. 7 is sectional view of a driving unit of a welding equipment according to a seventh embodiment of the invention, particularly a view showing the detail of a machining part thereof on which a manually operating handle is mounted for manually operating the driving unit.

PREFERRED EMBODIMENT OF THE INVENTION

First Embodiment (Fig. 1):

A driving unit of a welding equipment according to a first embodiment is described next.

In Fig. 1, a servomotor 1 comprises a winding 3 of a stator that is fixed to

an outer shell 2, a rotor magnetic pole 4 disposed at the inner periphery of the winding 3, and a rotary shaft 5 to which the rotor magnetic pole 4 is fixed, wherein the rotary shaft 5 is journaled by bearings 6 and supported by the outer shell 2 of the servomotor. The rotary shaft 5 is extended toward its output direction and the
5 extended portion constructs a screw shaft 7 on which a male screw 8 is provided to form a ball screw. A machining part 51 to which a manually operating handle is mounted is formed on the end of the rotary shaft 5 opposite to the output side of the rotary shaft 5.

A pressure application shaft 9 is connected, e.g., to a movable arm (not
10 shown) or swingable arm (not shown) by way of a trunnion shaft 10, or, e.g., to a workpiece placing table (not shown) at the front end thereof. The pressure application shaft 9 is journaled by a bearing 12 inside a frame case 11 so as to be reciprocated but not turned. The pressure application shaft 9 is formed of a hollow shaft and has a female screw which is directly provided on the inner
15 peripheral surface at the end thereof and meshes with the male screw 8, so as to form a ball nut 13. Accordingly, the ball nut 13 is integrally formed on the pressure application shaft 9. The rotary shaft 5 of a servomotor 1 is positioned substantially coaxially on the screw shaft 7.

A position detector 14 is engaged in the outer periphery of the rotary shaft 5
20 in the vicinity of the end thereof. Although the nut 13 is integrated with the pressure application shaft 9 in the first embodiment, it may be provided separately and may be integrated with the pressure application shaft 9 by welding or screwing at the end of the pressure application shaft 9.

The driving unit of a welding equipment of the first embodiment comprises,
25 as set forth above, the servomotor 1, rotary shaft 5, screw shaft 7, male screw 8, nut 13 and pressure application shaft 9. In the driving unit of a welding equipment having such a construction, when a three-phase ac current is supplied to the

winding 3 of the stator of the servomotor 1, in a state shown in Fig. 1, the rotor magnetic pole 4 is excited so that the rotary shaft 5 and screw shaft 7 are turned. As the screw shaft 7 is turned, the nut 13 meshing with the male screw 8 of the screw shaft 7 is advanced, so that the pressure application shaft 9 integrated with the nut 13 is also advanced. As a result, the movable arm, swingable arm, or work placing table, or the like performs pressure application operation by way of the trunnion shaft 10.

As mentioned in detail above, since the screw shaft 7 is integrated or substantially integrated with the rotary shaft 5 and the same bearing can be shared by the screw shaft 7 and the rotary shaft 5, the driving unit of a welding equipment can be reduced in length compared with the conventional driving unit of a welding equipment so that the length of the welding equipment is reduced to become compact. Further, since the moment of inertia applied to the servomotor 1 is reduced, moving response of the pressure application shaft 9 and the welding electrodes caused by the servomotor 1 is remarkably enhanced, realizing an efficient welding equipment that has an excellent operability.

As a baffling mechanism of the pressure application shaft 9, there is employed a known baffling mechanism such as a ball spline mechanism provided between the pressure application shaft 9 and the frame case 11, a mechanism using the bearing 12 and its rail.

Further, as shown in Fig. 1, if the machining part 51 on which the manually operating handle is mounted is formed on the end of the rotary shaft 5 opposite to the output side of the rotary shaft 5, the manually operating handle is mounted on the machining part 51 to turn the rotary shaft 5 manually to guide the pressure application shaft 9 to a desired position when the servomotor 1 is troubled.

Although in the first embodiment set forth above, a servomotor is employed as a motor, it is needless to say that a well-known motor such as a stepping motor,

an inverter motor, a reluctance motor or the like may be properly employed as the motor.

Second Embodiment (Fig. 2):

5 A driving unit of a welding equipment according to a second embodiment is described next.

10 A ball nut 21 on which a female screw 13 is provided is slidably disposed relative to a pressure application shaft 9 wherein the ball nut 21 is integrally provided on the pressure application shaft 9 by way of a baffling member 22 so that the former is not turned relative to the latter. A conical spring 23 formed of an elastic body is disposed between the tip end of the ball nut 21 and the pressure application shaft 9. A position detector 14 and an electromagnetic brake 24 are disposed on a rotary shaft 5.

15 Other components of the driving unit of a welding equipment are substantially the same as those of the first embodiment, and hence they are depicted by the same reference numerals and the explanation thereof is omitted.

20 Although a screw shaft 7 is turned as a servomotor 1 turns, the ball nut 21 is advanced relative to the pressure application shaft 9 while it is slid by the female screw 13 meshing with a male screw 8 formed on the screw shaft 7 as the screw shaft 7 is turned so as to press the conical spring 23 while the conical spring 23 is bent. Since the conical spring 23 formed of the elastic body is disposed on the axis of the pressure application shaft 9 through which the pressure application force exerts, the pressing force toward the conical spring 23 becomes a strong pressing force relative to the pressure application shaft selection means 9, resulting applying an advancing force to the pressure application shaft 9. As a result, the tip end of
25 the pressure application shaft 9 can press and fix a workpiece owing to the advancing force.

If the workpiece is pressed and fixed by the pressure application shaft 9, the

servomotor 1 stops its turning but operates the electromagnetic brake 24 to restraining the rotary shaft 5 from being turned, thereby rendering the pressure application shaft selection means 9 to continuously press and fix the workpiece with certainty.

5 Third Embodiment (Fig. 3):

A driving unit of a welding equipment according to a third embodiment is described next.

10 A hole 31 through which a screw shaft 7 is inserted is bored in a rotary shaft 5 of a servomotor 1. A power lock mechanism 32 formed by utilizing a wedging operation by an inner ring and an outer ring is disposed between the screw shaft 7 and the rotary shaft 5 so as to fix the rotary shaft 5 to the screw shaft 7. Accordingly, the screw shaft 7 and rotary shaft 5 are commonly journaled by common bearings 6. A nut 33 meshing with the male screw 8 formed on the screw shaft 7 is integrally fixed to the inner periphery of the pressure application shaft 9 at the end thereof.

15 Other components of the driving unit of a welding equipment are substantially the same of those of the first embodiment, and hence they are depicted by the same reference numerals and the explanation thereof is omitted.

20 In the third embodiment, the screw shaft 7 is turned as the servomotor 1 turns so that the nut 33 meshing with the male screw 8 formed on the screw shaft 7 is advanced as the screw shaft 7 is turned, whereby the pressure application shaft 9 is advanced.

25 As mentioned above, since the screw shaft 7 is substantially integrated with the rotary shaft 5 by a fixing unit utilizing a friction force and the bearing of the screw shaft 7 is shared with that of the rotary shaft 5 so that the length of the driving unit is reduced by the length of the shared bearing. As a result, the welding equipment is reduced in length and it becomes compact. Further, since the

moment of inertia applied to the servomotor 1 becomes small, moving response of the pressure application shaft 9 and the welding electrodes caused by the servomotor 1 is remarkably enhanced, realizing a welding equipment that is operable and efficiently.

5. > INS C1
Further, ~~since the rotary shaft 5 and ball screw shaft 7 are separately~~ provided, the combination thereof can be freely selected to enhance flexibility, assembly and maintenance thereof, thereby forming the driving unit of a welding equipment so as to serve a motor-operated welding equipment that is compact and ~~has an excellent operability.~~

10 Since the screw shaft 7 and the rotary shaft 5 are locked with each other by fastening means utilizing a friction force, the screw shaft 7 can be easily pulled out from the servomotor 1 by unlocking the fastening means.

15 00220-032200
The fastening means ~~utilizing a friction force is not limited to that utilizing a~~ wedging operation as set forth above but includes an apparatus having a principle for generating pressure in liquid medium sealed in a sleeve and expanding the sleeve ~~to perform fastening or the like.~~

Fourth Embodiment (Fig. 4):

A driving unit of a welding equipment according to a fourth embodiment is described next.

20 In Fig. 4, a rotary shaft 5 of a servomotor 1 is made hollow to form a hollow portion and it is journaled by bearings 6 and supported by an outer shell 2 of the servomotor 1. A ball screw shaft 7 is penetrated into the hollow portion of the rotary shaft 5. A ring 41 and a nut 42 are disposed on one end of the ball screw shaft 7 utilizing a friction force so as to fix the ball screw shaft 7 to the rotary shaft 5. Accordingly, the ball screw shaft 7 is journaled by the common bearings 6 that are shared by the rotary shaft 5. A ball screw 8 is screwed on the other end of the ball screw shaft 7 and is disposed outside the servomotor 1.

A pressure application shaft 9 is journaled by a bearing 12 inside a housing so as to be reciprocated but not turned, while a ball nut 13 meshing with the ball screw 8 is substantially integrally provided with the rear end of the pressure application shaft 9.

5
1
C
3
5
7
9
11
13
15
17
19
21
23
25
27
29
31
33
35
37
39
41
43
45
47
49
51
53
55
57
59
61
63
65
67
69
71
73
75
77
79
81
83
85
87
89
91
93
95
97
99
101
103
105
107
109
111
113
115
117
119
121
123
125
127
129
131
133
135
137
139
141
143
145
147
149
151
153
155
157
159
161
163
165
167
169
171
173
175
177
179
181
183
185
187
189
191
193
195
197
199
201
203
205
207
209
211
213
215
217
219
221
223
225
227
229
231
233
235
237
239
241
243
245
247
249
251
253
255
257
259
261
263
265
267
269
271
273
275
277
279
281
283
285
287
289
291
293
295
297
299
301
303
305
307
309
311
313
315
317
319
321
323
325
327
329
331
333
335
337
339
341
343
345
347
349
351
353
355
357
359
361
363
365
367
369
371
373
375
377
379
381
383
385
387
389
391
393
395
397
399
401
403
405
407
409
411
413
415
417
419
421
423
425
427
429
431
433
435
437
439
441
443
445
447
449
451
453
455
457
459
461
463
465
467
469
471
473
475
477
479
481
483
485
487
489
491
493
495
497
499
501
503
505
507
509
511
513
515
517
519
521
523
525
527
529
531
533
535
537
539
541
543
545
547
549
551
553
555
557
559
561
563
565
567
569
571
573
575
577
579
581
583
585
587
589
591
593
595
597
599
601
603
605
607
609
611
613
615
617
619
621
623
625
627
629
631
633
635
637
639
641
643
645
647
649
651
653
655
657
659
661
663
665
667
669
671
673
675
677
679
681
683
685
687
689
691
693
695
697
699
701
703
705
707
709
711
713
715
717
719
721
723
725
727
729
731
733
735
737
739
741
743
745
747
749
751
753
755
757
759
761
763
765
767
769
771
773
775
777
779
781
783
785
787
789
791
793
795
797
799
801
803
805
807
809
811
813
815
817
819
821
823
825
827
829
831
833
835
837
839
841
843
845
847
849
851
853
855
857
859
861
863
865
867
869
871
873
875
877
879
881
883
885
887
889
891
893
895
897
899
901
903
905
907
909
911
913
915
917
919
921
923
925
927
929
931
933
935
937
939
941
943
945
947
949
951
953
955
957
959
961
963
965
967
969
971
973
975
977
979
981
983
985
987
989
991
993
995
997
999
1001
1003
1005
1007
1009
1011
1013
1015
1017
1019
1021
1023
1025
1027
1029
1031
1033
1035
1037
1039
1041
1043
1045
1047
1049
1051
1053
1055
1057
1059
1061
1063
1065
1067
1069
1071
1073
1075
1077
1079
1081
1083
1085
1087
1089
1091
1093
1095
1097
1099
1101
1103
1105
1107
1109
1111
1113
1115
1117
1119
1121
1123
1125
1127
1129
1131
1133
1135
1137
1139
1141
1143
1145
1147
1149
1151
1153
1155
1157
1159
1161
1163
1165
1167
1169
1171
1173
1175
1177
1179
1181
1183
1185
1187
1189
1191
1193
1195
1197
1199
1201
1203
1205
1207
1209
1211
1213
1215
1217
1219
1221
1223
1225
1227
1229
1231
1233
1235
1237
1239
1241
1243
1245
1247
1249
1251
1253
1255
1257
1259
1261
1263
1265
1267
1269
1271
1273
1275
1277
1279
1281
1283
1285
1287
1289
1291
1293
1295
1297
1299
1301
1303
1305
1307
1309
1311
1313
1315
1317
1319
1321
1323
1325
1327
1329
1331
1333
1335
1337
1339
1341
1343
1345
1347
1349
1351
1353
1355
1357
1359
1361
1363
1365
1367
1369
1371
1373
1375
1377
1379
1381
1383
1385
1387
1389
1391
1393
1395
1397
1399
1401
1403
1405
1407
1409
1411
1413
1415
1417
1419
1421
1423
1425
1427
1429
1431
1433
1435
1437
1439
1441
1443
1445
1447
1449
1451
1453
1455
1457
1459
1461
1463
1465
1467
1469
1471
1473
1475
1477
1479
1481
1483
1485
1487
1489
1491
1493
1495
1497
1499
1501
1503
1505
1507
1509
1511
1513
1515
1517
1519
1521
1523
1525
1527
1529
1531
1533
1535
1537
1539
1541
1543
1545
1547
1549
1551
1553
1555
1557
1559
1561
1563
1565
1567
1569
1571
1573
1575
1577
1579
1581
1583
1585
1587
1589
1591
1593
1595
1597
1599
1601
1603
1605
1607
1609
1611
1613
1615
1617
1619
1621
1623
1625
1627
1629
1631
1633
1635
1637
1639
1641
1643
1645
1647
1649
1651
1653
1655
1657
1659
1661
1663
1665
1667
1669
1671
1673
1675
1677
1679
1681
1683
1685
1687
1689
1691
1693
1695
1697
1699
1701
1703
1705
1707
1709
1711
1713
1715
1717
1719
1721
1723
1725
1727
1729
1731
1733
1735
1737
1739
1741
1743
1745
1747
1749
1751
1753
1755
1757
1759
1761
1763
1765
1767
1769
1771
1773
1775
1777
1779
1781
1783
1785
1787
1789
1791
1793
1795
1797
1799
1801
1803
1805
1807
1809
1811
1813
1815
1817
1819
1821
1823
1825
1827
1829
1831
1833
1835
1837
1839
1841
1843
1845
1847
1849
1851
1853
1855
1857
1859
1861
1863
1865
1867
1869
1871
1873
1875
1877
1879
1881
1883
1885
1887
1889
1891
1893
1895
1897
1899
1901
1903
1905
1907
1909
1911
1913
1915
1917
1919
1921
1923
1925
1927
1929
1931
1933
1935
1937
1939
1941
1943
1945
1947
1949
1951
1953
1955
1957
1959
1961
1963
1965
1967
1969
1971
1973
1975
1977
1979
1981
1983
1985
1987
1989
1991
1993
1995
1997
1999
2001
2003
2005
2007
2009
2011
2013
2015
2017
2019
2021
2023
2025
2027
2029
2031
2033
2035
2037
2039
2041
2043
2045
2047
2049
2051
2053
2055
2057
2059
2061
2063
2065
2067
2069
2071
2073
2075
2077
2079
2081
2083
2085
2087
2089
2091
2093
2095
2097
2099
2101
2103
2105
2107
2109
2111
2113
2115
2117
2119
2121
2123
2125
2127
2129
2131
2133
2135
2137
2139
2141
2143
2145
2147
2149
2151
2153
2155
2157
2159
2161
2163
2165
2167
2169
2171
2173
2175
2177
2179
2181
2183
2185
2187
2189
2191
2193
2195
2197
2199
2201
2203
2205
2207
2209
2211
2213
2215
2217
2219
2221
2223
2225
2227
2229
2231
2233
2235
2237
2239
2241
2243
2245
2247
2249
2251
2253
2255
2257
2259
2261
2263
2265
2267
2269
2271
2273
2275
2277
2279
2281
2283
2285
2287
2289
2291
2293
2295
2297
2299
2301
2303
2305
2307
2309
2311
2313
2315
2317
2319
2321
2323
2325
2327
2329
2331
2333
2335
2337
2339
2341
2343
2345
2347
2349
2351
2353
2355
2357
2359
2361
2363
2365
2367
2369
2371
2373
2375
2377
2379
2381
2383
2385
2387
2389
2391
2393
2395
2397
2399
2401
2403
2405
2407
2409
2411
2413
2415
2417
2419
2421
2423
2425
2427
2429
2431
2433
2435
2437
2439
2441
2443
2445
2447
2449
2451
2453
2455
2457
2459
2461
2463
2465
2467
2469
2471
2473
2475
2477
2479
2481
2483
2485
2487
2489
2491
2493
2495
2497
2499
2501
2503
2505
2507
2509
2511
2513
2515
2517
2519
2521
2523
2525
2527
2529
2531
2533
2535
2537
2539
2541
2543
2545
2547
2549
2551
2553
2555
2557
2559
2561
2563
2565
2567
2569
2571
2573
2575
2577
2579
2581
2583
2585
2587
2589
2591
2593
2595
2597
2599
2601
2603
2605
2607
2609
2611
2613
2615
2617
2619
2621
2623
2625
2627
2629
2631
2633
2635
2637
2639
2641
2643
2645
2647
2649
2651
2653
2655
2657
2659
2661
2663
2665
2667
2669
2671
2673
2675
2677
2679
2681
2683
2685
2687
2689
2691
2693
2695
2697
2699
2701
2703
2705
2707
2709
2711
2713
2715
2717
2719
2721
2723
2725
2727
2729
2731
2733
2735
2737
2739
2741
2743
2745
2747
2749
2751
2753
2755
2757
2759
2761
2763
2765
2767
2769
2771
2773
2775
2777
2779
2781
2783
2785
2787
2789
2791
2793
2795
2797
2799
2801
2803
2805
2807
2809
2811
2813
2815
2817
2819
2821
2823
2825
2827
2829
2831
2833
2835
2837
2839
2841
2843
2845
2847
2849
2851
2853
2855
2857
2859
2861
2863
2865
2867
2869
2871
2873
2875
2877
2879
2881
2883
2885
2887
2889
2891
2893
2895
2897
2899
2901
2903
2905
2907
2909
2911
2913
2915
2917
2919
2921
2923
2925
2927
2929
2931
2933
2935
2937
2939
2941
2943
2945
2947
2949
2951
2953
2955
2957
2959
2961
2963
2965
2967
2969
2971
2973
2975
2977
2979
2981
2983
2985
2987
2989
2991
2993
2995
2997
2999
3001
3003
3005
3007
3009
3011
3013
3015
3017
3019
3021
3023
3025
3027
3029
3031
3033
3035
3037
3039
3041
3043
3045
3047
3049
3051
3053
3055
3057
3059
3061
3063
3065
3067
3069
3071
3073
3075
3077
3079
3081
3083
3085
3087
3089
3091
3093
3095
3097
3099
3101
3103
3105
3107
3109
3111
3113
3115
3117
3119
3121
3123
3125
3127
3129
3131
3133
3135
3137
3139
3141
3143
3145
3147
3149
3151
3153
3155
3157
3159
3161
3163
3165
3167
3169
3171
3173
3175
3177
3179
3181
3183
3185
3187
3189
3191
3193
3195
3197
3199
3201
3203
3205
3207
3209
3211
3213
3215
3217
3219
3221
3223
3225
3227
3229
3231
3233
3235
3237
3239
3241
3243
3245
3247
3249
3251
3253
3255
3257
3259
3261
3263
3265
3267
3269
3271
3273
3275
3277
3279
3281
3283
3285
3287
3289
3291
3293
3295
3297
3299
3301
3303
3305
3307
3309
3311
3313
3315
3317
3319
3321
3323
3325
3327
3329
3331
3333
3335
3337
3339
3341
3343
3345
3347
3349
3351
3353
3355
3357
3359
3361
3363
3365
3367
3369
3371
3373
3375
3377
3379
3381
3383
3385
3387
3389
3391
3393
3395
3397
3399
3401
3403
3405
3407
3409
3411
3413
3415
3417
3419
3421
3423
3425
3427
3429
3431
3433
3435
3437
3439
3441
3443
3445
3447
3449
3451
3453
3455
3457
3459
3461
3463
3465
3467
3469
3471
3473
3475
3477
3479
3481
3483
3485
3487
3489
3491
3493
3495
3497
3499
3501
3503
3505
3507
3509
3511
3513
3515
3517
3519
3521
3523
3525
3527
3529
3531
3533
3535
3537
3539
3541
3543
3545
3547
3549
3551
3553
3555
3557
3559
3561
3563
3565
3567
3569
3571
3573
3575
3577
3579
3581
3583
3585
3587
3589
3591
3593
3595
3597
3599
3601
3603
3605
3607
3609
3611
3613
3615
3617
3619
3621
3623
3625
3627
3629
3631
3633
3635
3637
3639
3641
3643
3645
3647
3649
3651
3653
3655
3657
3659
3661
3663
3665
3667
3669
3671
3673
3675
3677
3679
3681
3683
3685
3687
3689
3691
3693
3695
3697
3699
3701
3703
3705
3707
3709
3711
3713
3715
3717
3719
3721
3723
3725
3727
3729
3731
3733
3735
3737
3739
3741
3743
3745
3747
3749
3751
3753
3755
3757
3759
3761
3763
3765
3767
3769
3771
3773
3775
3777
3779
3781
3783
3785
3787
3789
3791
3793
3795
3797
3799
3801
3803
3805
3807
3809
3811
3813
3815
3817
3819
3821
3823
3825
3827
3829
3831
3833
3835
3837
3839
3841
3843
3845
3847
3849
3851
3853
3855
3857
3859
3861
3863
3865
3867
3869
3871
3873
3875
3877
3879
3881
3883
3885
3887
3889
3891
3893
3895
3897
3899
3901
3903
3905
3907
3909
3911
3913
3915
3917
3919
3921
3923
3925
3927
3929
3931
3933
3935
3937
3939
3941
3943
3945
3947
3949
3951
3953
3955
3957
3959
3961
3963
3965
3967
3969
3971
3973
3975
3977
3979
3981
3983
3985
3987
3989
3991
3993
3995
3997
3999
4001
4003
4005
4007
4009
4011
4013
4015
4017
4019
4021
4023
4025
4027
4029
4031
4033
4035
4037
4039
4041
4043
4045
4047
4049
4051
4053
4055
4057
4059
4061
4063
4065
4067
4069
4071
4073
4075
4077
4079
4081
4083
4085
4087
4089
4091
4093
4095
4097
4099
4101
4103
4105
4107
4109
4111
4113
4115
4117
4119
4121
4123
4125
4127
4129
4131
4133
4135
4137
4139
4141
4143
4145
4147
4149
4151
4153
4155
4157
4159
4161
4163
4165
4167
4169
4171
4173
4175
4177
4179
4181
4183
4185
4187
4189
4191
4193
4195
4197
4199
4201
4203
4205
4207
4209
4211
4213
4215
4217
4219
4221
4223
4225
4227
4229
4231
4233
4235
4237
4239
4241
4243
4245
4247
4249
4251
4253
4255
4257
4259
4261
4263
4265
4267
4269
42

other by fastening means utilizing a friction force such as a wedging operation, they can be fixed to each other without requiring a troublesome operation such as shrinkage fit or cold shrinkage fit. It is possible to easily pull out the ball screw shaft 7 from the servomotor 1 by unlocking the ball screw shaft 7 from the rotary shaft 5. Further, since a machining part 51 is provided on one end of the ball screw shaft 7 on which a manually operating handle is mounted, the ball screw shaft 7 is turned manually by mounting the manually operating handle (not shown) on the machining part 51 when the servomotor 1 is troubled so as to advance the pressure application shaft 9 so that a movable arm or a swingable arm can be guided to a desired opening position.

Fifth Embodiment (Fig. 5):

A driving unit of a welding equipment according to a fifth embodiment is described next.

In Fig. 5, a rotary shaft 5 of the servomotor 1 is formed of a hollow shaft and is supported by the outer shell 2 of the servomotor 1 by way of bearings 6. Further, a ball screw shaft 7 is positioned in the core of the axis of the servomotor 1 and is fixed to the rotary shaft 5 by a power lock mechanism. A screw 8 of the ball screw shaft 7 is screwed with a ball nut 13 provided on the pressure application shaft 9 so that a rotary force of the rotary shaft 5 of the servomotor 1 is converted into a reciprocating motion so as to reciprocate the pressure application shaft 9. This construction is substantially the same as the fourth embodiment, and hence other components are depicted by the same reference numerals and the detail of the construction is omitted.

The ball screw shaft 7 positioned in the core of the axis of the servomotor 1 and fixed to the rotary shaft 5 by the power lock mechanism is extended rearward from the body of the servomotor 1 and is connected to a position detector 14.

Although the manually operating part 51 is disposed at the rear of the

position detector 14 in the fourth embodiment, the manually operating part is however positioned as follows in the fifth embodiment.

5 ~~That is, a relatively large diameter gear 61 forming a driven part for~~
transmitting the of the servomotor 1 is fixed to the ball screw shaft 7 between the
front of the position detector 14 and the rear of the body of the servomotor 1. A
relatively small diameter gear 62 forming a manually operating driving part for
applying a turning torque to the gear 61 of the driven part is positioned eccentrically
from the rotary central axis of the servomotor 1, and the gears 61 and 62 mesh
directly with each other. The gears 61 and 62 may be connected with each other by
10 way of a serrated toothed belt (not shown).

A machining part 63 comprising, e.g., a manually turning unit such as a
machining hole or machining projection is formed on the gear 62 of the driving part
so that the gear 62 is operated by a handle or the like by way of a manually
operating hole 64.

15 When the pressure application shaft 9 can not perform a reciprocating
motion owing to a trouble in the servomotor 1 or an operation system of the
welding equipment, a manually operating handle (not shown) is mounted on the
machining part 63 formed on the gear 62 of the driving part so that the ball screw
shaft 7 is turned by way of the gears 61, 62 by turning the handle. As a result, the
20 pressure application shaft 9 performs a reciprocating motion so that the pressure
application shaft 9 is moved to a desired standby position

Meanwhile, since electronic components or the like are generally disposed
on the entire back surface of the position detector 14 that is positioned coaxially
with the servomotor 1, the ball screw shaft 7 hardly penetrates the position detector
25 14. However, according to the invention, while the ball screw shaft 7 does not
penetrate the position detector 14, the gear 61 of the driven part for transmitting the
of the servomotor 1 is formed on the rotary central axis of the servomotor 1

between the front of the position detector 14 and the rear of the body of the servomotor image pickup means 1 and the gear 33 for applying a turning torque to the gear 61 is positioned eccentrically from the rotary central axis of the servomotor 1. As a result, the gear 62 for applying a turning torque to the gear 61 is easily provided to render the driving unit of a welding equipment compact as a whole.

Although the gear 61 of the driven part is formed on the ball screw shaft 7 for transmitting the torque of the servomotor 1, the gear 61 of the driven part for driving the torque may be provided instead of the ball screw shaft 7 in the case that the rotary shaft 5 is extended rearward the body of the servomotor 1 as illustrated in the first to third embodiments.

Sixth Embodiment (Fig. 6):

A driving unit of a welding equipment according to a sixth embodiment is described next.

~~A gear 62 of a driving part for driving a gear 61 forming a driven part for transmitting the torque of a servomotor 1 is made standby when the servomotor 1 operates. That is, a returning spring 72 formed of an elastic body is biased in guide shaft 71 for holding the gear 62 to form a standby unit. The guide shaft 71 is a latch input terminal LE formed in a housing 73 of a position detector 14 and it is journaled by a bearing 76 of a bearing holding member 75 screwed in the entrance of the hole 74. Depicted by 77 is a manually operating knob and 78 is a dust seal.~~

In the sixth embodiment, the gear 62 is normally forced to standby upward by the returning spring 72 serving as a standby unit, and hence it does not mesh with the gear 61 so that the gear 62 is not turned when the motor operates.

When a pressure application shaft 9 can not perform the reciprocating motion, the manually operating knob 77 is first pressed against the urging force of the returning spring 72 so that the gear 62 meshes with the gear 61. At this time, when the manually operating knob 77 is turned to turn the gear 62, a ball screw

shaft 7 or rotary shaft 5 is turned by way of the gears 62, 61 so that the pressure application shaft 9 performs a reciprocating motion, and hence the pressure application shaft 9 is moved to a desired standby position.

As mentioned above, since the gear 62 is not turned when the motor
5 operates normally, wasting energy consumption can be reduced.

Seventh Embodiment (Fig. 7):

A driving unit of a welding equipment according to a seventh embodiment is described next.

In the seventh embodiment shown in Fig. 7, a gear 62 of a driving part for
10 driving a gear 61 of a driven part for transmitting the torque of a servomotor 1 is pulled off from a housing 73 of a position detector 14 when the servomotor 1 operates. That is, the diameter of a guide shaft 71 is slightly made larger than that of the gear 62 and the diameter of a hole 74 is formed in the manner that the guide shaft 71 can pass through the hole 74 together with the gear 62. A notched cover
15 81 formed of rubber is positioned at the entrance of the hole 74 for closing the entrance of the hole 74 so that a foreign matter such as dust is prevented from entering the hole 74 when the gear 62 is removed from the motor 1.

In this seventh embodiment, the gear 62 is normally taken out from the motor 1 by a manually operating knob 77 so that the gears 61 and 62 do not mesh
20 with each other, and hence the gear 61 merely runs idle when the motor 1 operates.

As mentioned above, when the pressure application shaft 9 can not perform the reciprocating motion, the gear 62 is first inserted into the hole 74 using the manually operating knob 77 to permit the gear 62 to mesh with the gear 61. Then, when the gear 62 is turned by turning the manually operating knob 77, the ball
25 screw shaft 7 or the rotary shaft 5 is turned by way of the gears 61 and 62 to permit the pressure application shaft 9 to perform the reciprocating motion so that the pressure application shaft 9 can be moved to a desired standby position.

Also in the seventh embodiment, since the gear 61 merely runs idle when the motor normally operates, wasting energy consumption is reduced.

Since the driving unit of a welding equipment comprises a screw shaft provided integrally with or substantially integrally with a rotary shaft of the motor, a
5 nut provided integrally with or substantially integrally with the pressure application shaft and is screwed with a screw of the screw shaft, and a baffling mechanism provided on the pressure application shaft, wherein the rotary shaft of the motor is positioned substantially coaxially with the screw shaft and a rotary force outputted from the rotary shaft of the motor is converted into a reciprocating
10 motion of the pressure application shaft, it is possible to provide the driving unit of a welding equipment capable of reducing the size of the driving unit, of reducing the moment of inertia, and of being compact and having an excellent operability.

Further, since the screw shaft is substantially integrally provided on the rotary shaft of the motor by fixing the former to the latter utilizing a friction force, it
15 is possible to provide the driving unit of a welding equipment capable of fixing both the screw shaft and the rotary shaft to each other without requiring a troublesome operation such as shrinkage fit or cold shrinkage fit.

Still further, since the elastic body is disposed on the axis of the pressure application shaft through which the pressure application force exerts, and the
20 electromagnetic brake is disposed on the rotary shaft of the motor, it is possible to provide the driving unit of a welding equipment capable of securing the application of pressure to a workpiece by a pressure application shaft.

or screw shaft opposite to the output side of the rotary shaft, on which a manually operating handle is mounted, it is possible to provide the driving unit of a
25 welding equipment capable of moving a pressure application shaft to a desired standby position when a motor is troubled.